



PATENT

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to Mail Stop Certificate Of Correction Branch Commissioner For Patents, P. O. Box 1450,

Alexandria VA 22313-1

Vaup Jacob Red 35 593

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Numbe:

6.922.87**7**

Certificate

Issued:

August 2, 2005

MAY 1 5 2006

Serial Number:

09/878,743 June 11, 2001

of Correction

Filed: Group Art Unit:

1732

Examiner:

Mary Lynn F. Theisen

Applicant:

Title:

John Linville, Donald R. Maier and Patrick M. Saaf CASKET LID AND METHOD OF MAKING SAME

Cincinnati, Ohio 45202

May 8, 2006

Mail Stop Certificate of Corrections Branch Commissioner for Patents P. O. Box 1450 Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R. §1.322(a)

Attached in duplicate is Form PTO-SB/44 with at least one copy being suitable for printing.

The following is the page and line number where the error occurs in the application file:

January 4, 2002, Information Disclosure Statement, Form PTO-1449, page 3, entry 4, reads -- 3,729,786; --, not "3,729,785".

March 7, 2003 Response Under 37 C.F.R. §1.111, Claim 24, page 4, line 10, reads: -- with said wood grain pattern formed in said crown on the other side of the -- , not "with said wood grain pattern formed in said crown on the other side or the".

Specification, Claim 27, page 33, line 10, reads: -- continuous with said wood grain pattern formed in said --, not "continuous with said wood grain pattern fanned in said".

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

Bv:

Wayne L.\ Jacob Reg. No. 85.553

2700 Carew Tower 441 Vine Street Cincinnati, OH 45202

Phone: (513) 241-2324 Fax: (513) 421-7269

PTO/SB/44 (04-05)
Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

				_		
PATENT NO. : 6,922,877				Page	<u>1</u> 0	f1_
APPLICATION NO.: 09/878,743						
ISSUE DATE : 08/02/05						
INVENTOR(S) : John E. Linville	Donald R. Maier an	d Patrick M. Saaf				
It is certified that an error ap is hereby corrected as shown bel		ar in the above-id	entified patent and t	nat said L	.etters	Patent
Column 1, Page 2, line 16, r 5/1973 Walding	eads: "3,729,785 A	5/1973 Walding"	when it should read	:3,729,	786 A	
Column 7, Claim 1, line 45, read: said crown on the other			r the longitudinal axi	s of" whe	n it sh	ould
Column 8, Claim 4, line 20, should read: grain pattern form				e of the"	when i	it

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Wayne L. Jacobs

WOOD, HERRON & EVANS, L.L.P.

2700 CAREW TOWER, 441 VINE STREET, CINCINNATI, OH 45202

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.



U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page	1	of _	_ 1	

PATENT NO.

: 6,922,877

APPLICATION NO.: 09/878,743

ISSUE DATE

: 08/02/05

INVENTOR(S)

John E. Linville, Donald R. Maier and Patrick M. Saaf

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, Page 2, line 16, reads: "3,729,785 A 5/1973 Walding" when it should read: --3,729,786 A 5/1973 Walding --.

Column 7, Claim 1, line 45, reads: "said crown on the other side or the longitudinal axis of" when it should read: -- said crown on the other side of the longitudinal axis of --.

Column 8, Claim 4, line 20, reads: "grain pattern fanned in said crown on the other side of the" when it should read: -- grain pattern formed in said crown on the other side of the --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Wayne L. Jacobs

WOOD, HERRON & EVANS, L.L.P.

2700 CAREW TOWER, 441 VINE STREET, CINCINNATI, OH 45202

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

